



## TO WHOM IT MAY CONCERN

The Guru Nanak Public School Dalhousie Distt, Chamba H.P. was inspected by A.E along with Junior Engineer and Headmaster of the above said school on dated 24-01-2024. During inspection Structural drawing approved by competent authority were not produced. Therefore structural stability and earthquake resistance of structure cannot be assured. Also at this stage it is not possible to analyse and check the stability of the existing building as hidden dimension and reinforcement if any, could not be verified during the inspection. This department will not be responsible for any type of loss of life or property etc, if this structure fails under any circumstances.


However as per visual inspection, the building has been found safe to run school classes for the financial year 2024-25. Therefore, the certificate is hereby issued for the year 2024-25 on the basis of physical appearance of the building only. No Officer/Official of this office will attend any plea in any Hon'ble Court of Law in case of any dispute.



Junior Engineer  
Dalhousie Sub Division  
HPPWD Dalhousie



Assistant Engineer  
Dalhousie Sub Division  
HPPWD Dalhousie



Executive Engineer  
Dalhousie Division  
HPPWD Dalhousie