

## **TO WHOM IT MAY CONCERN**

The Guru Nanak Public School Dalhousie Distt, Chamba H.P. was inspected by A.E along with Junior Engineer and Headmaster of the above said school on dated 10-02-2025 During inspection Structural drawing approved by competent authority were not produced. Therefore structural stability and earthquake resistance of structure cannot be assured. Also at this stage it is not possible to analyse and check the stability of the Existing building as hidden dimension and reinforcement if any, could not be verified during the inspection. This department will not be responsible for any type of loss of life or property etc, if this structure fails under any circumstances.

However as per visual inspection, the building has been found safe to run school classes for the financial year 2025-26. Therefore, the certificate is hereby issued for the year 2025-26 on the basis of physical appearance of the building only. No Officer/Official of this office will attend any plea in any Hon'ble Court of Law in case of any dispute.



Junior Engineer  
Dalhousie Sub Division  
HPPWD Dalhousie



Assistant Engineer  
Dalhousie Sub Division  
HPPWD Dalhousie



Executive Engineer  
Dalhousie Division  
HPPWD Dalhousie

માસિક કા બાબી કુદુરુ કુદુરુ કુદુરુ  
કુદુરુ નાનક પાંચાંક કુદુરુ કુદુરુ  
દવાર કાંદુ કુદુરુ કુદુરુ કુદુરુ  
કુદુરુ કુદુરુ

માસિક કા બાબી કુદુરુ કુદુરુ  
કુદુરુ

11/02/25

માસિક કા બાબી  
યાદું  
દવાર  
કુદુરુ

VRO sign c/s


  
VRO  
TEHSILDAR 125  
DALHOUSIE

नेकले अवसं लेटों ततीमा मुहाल मोती टिक्का नं. ४०-३४६/३  
तदसील डलहोडी जिला चम्पा हिंदूपूरा।

ਤਦਸੀਲ ਲੋਧੀ ਜਿਲ੍ਹਾ ਚੱਕਾ ਹਿੰਦੂ।

प्राचीन वा उपर्याप्त

10 मीटर प्रति सेकंडी मीटर



नेट + जैसा पहा व हैखा गया

वैसा लिखा गया जहाँ नहीं पढ़ा

ग्राम वस्ती (x) का निशान लगाया

ग्रन्थालय

Steffen  
11/02/2025